

PROJECT REFERENCE





ABOUT THE REINSTATEMENT

Remove all glass partitions and plaster walls, all built-in furniture, workstations, racks, cabinets and roller shutters

Remove any non-standard/damaged false ceiling Remove all floor finishes, such as carpets, tiles Remove all wires, conduits, trucking, water pipes, cables and data lines

Restore the ceiling system to its original state
Restore the raised floor system to its original state
Restore the lighting system to its original state
Restore the air conditioning (A.C) system to its original state

Restore the F.S to its original state

Repaint the walls to their original

colors

CLIENT INFORMATION

Tenants are required to engage the following Recommended Contractors: -

Recommended Contractors

Fire Services & Plumbing & Draining

1. Thomson (E&M)Contracting Ltd.

Air Conditioning System

- 1. Jardine Technnical Services
- 2. ATAL Engineering Ltd.

Electrical

1. Triple Faith Engineering & Supply Ltd.

Reinstatement Costing

HK350-380 Per sq. ft/ Net